0011



DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210

Kathleen Clarke **Executive Director**

Michael O. Leavitt

Governor

Lowell P. Braxton Division Director

PO Box 145801 Salt Lake City, Utah 84114-5801

801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

INSPECTION REPORT

Partial:		Exploration:
Inspection Date &	Time:	1:00pm 1:00pm
Date of Las	st Inspection: 04/12	2/2001_

Mine Name: Soldier Canyon Mine County: Carbon Permit Number: C	
Permittee and/or Operator's Name: Canyon Fuel Company	
Business Address: P.O. Box 1029, Wellington, Utah 84542	0.1
Type of Mining Activity: Underground XXX Surface Prep. Plant	_ Other
Company Official(s): Chris Hansen, David Spillman	
State Official(s): Stephen J. Demczak Federal Official(s): None	
Weather Conditions: 80's, Clear Skies	
Existing Acreage: Permitted 6624.64 Disturbed 24.32 Regraded Se	eded
Status: Active XXX	

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below. 2.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	DEDICATE CHANCE TRANSFER DENEWAL CALE	EVALUATED [X]	<u>N/A</u> ∐	COMMENTS [X]	NOV/ENF
	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE SIGNS AND MARKERS	[X]		[X]	
2.		[X]	П	[X]	Ξ
3.	TOPSOIL HYDROLOGIC BALANCE:	171	1-1	1221	
4.		[X]	П	[X]	Ц
		[X]		[X]	$\overline{\Box}$
	A THE STATE OF THE COLUMN OF A CURE C	[X]			
	d. WATER MONITORING	[X]	ü	<u>[X]</u>	Ξ
	THE LIE WAS A STATE OF THE STAT	[X]		[X]	Ξ
5.	e. EFFLUENT LIMITATIONS EXPLOSIVES	[X]	\Box	<u>[X]</u>	$\overline{\Box}$
5. 6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[X]	\Box		\Box
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[X]		<u>[X]</u>	
8.	NONCOAL WASTE	<u>[X]</u>	\Box	[X]	
9.	PROTECTION OF FISH, WILDLIFE AND RELATED	<u>[X]</u>	\Box	П	\Box
٠.	ENVIRONMENTAL ISSUES		=		
10.	SLIDES AND OTHER DAMAGE	[X]	П		\Box
	CONTEMPORANEOUS RECLAMATION	<u>[X]</u>	$\overline{\Box}$	\Box	\Box
	BACKFILLING AND GRADING	[X]	\Box	\Box	\Box
	REVEGETATION	[X]	\Box	П	П
	SUBSIDENCE CONTROL	[X]	\Box	[X]	\Box
	CESSATION OF OPERATIONS	[X]	\Box	[X]	
16.	ROADS:				
	a. CONSTRUCTION/MAINTENANCE/SURFACING	[X]	\square		\Box
	b. DRAINAGE CONTROLS	[X]	\Box	\Box	Ц
17.	OTHER TRANSPORTATION FACILITIES	[X]	\Box		Ц
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]	\Box	[X]	· []
	AVS CHECK (4th Quarter- April, May, June)	[X]	\Box		П
	AIR QUALITY PERMIT	[X]	\Box	[X]	Ц
	BONDING & INSURANCE	[X]	\Box	[X]	

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/007/018

DATE OF INSPECTION: 07/12/2001

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The Reclamation Agreement is being reviewed at the Division. Upon review of the agreement, a signed copy will be sent back to the operator.

2. SIGNS AND MARKERS

The identification signs were inspected. These signs are located at the gates to the mine's property. The required information was displayed correctly.

3. TOPSOIL

The topsoil piles were inspected with no signs of wind or water erosion.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions were spot-checked throughout the disturbed area. These diversions had no water flow and were maintained as designed.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The sediment pond was inspected on May 5, 2001 for second quarter. No hazardous conditions were reported. The sediment pond did contain a small amount of water due to the recent rain storms.

4D. HYDROLOGIC BALANCE: WATER MONITORING

The first quarter water monitoring was submitted to the Division. The inspector reviewed the electronic water data prior to the inspection. The permittee has met the requirements of the Mining and Reclamation Plan for the submittal of the first quarter water information. All accessible water sites had the required, parameters, and holding times taken.

The permittee has not received second quarter water information from the lab at this time. The second quarter information will be electronically submitted to the Division by the end of the quarter. The permittee plans on taking third quarter water samples by the end of the quarter.

4E. HYDROLOGIC BALANCE: EFFLUENT LIMITATIONS

There were no discharges form the sediment pond from Soldier Creek Mine for first and second quarter.

The UPDES permit number is UT0023680, and became effective on April 1, 1996. This permit will expire on March 31, 2001. The permittee has submitted the necessary information for renewal and is waiting for DEQ/DWQ to issue a new permit. Currently, there are three water monitoring sites: (1) site 001-A, mine water discharge through a 30-inch culvert; (2) site 002-A, sediment pond discharge; and (3) site 003-A, mine water discharge near #2 fan.

5. EXPLOSIVES

No explosives were on site.

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/007/018

DATE OF INSPECTION: 07/12/2001

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

Soldier Creek has no refuse pile.

8. NONCOAL WASTE

The disturbed area had some non-coal waste material by the timber yard.

14. SUBSIDENCE CONTROL

The subsidence survey was taken on October 17, 2000. This information is available in the 2000 Annual Report located at the Division.

15. CESSATION OF OPERATIONS

The mine is in temporary cessation of operations and quarterly complete inspections are made. It will be several years before mining is anticipated to resume.

18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

No new structures were built in the second quarter.

20. AIR QUALITY PERMIT

The Air Quality Permit was issued on April 25, 1994; the permit number is DAQE-334-94.

21. BONDING AND INSURANCE

Insurance will expire on July 31, 2001 and is issued by Federal Insurance Co. The acord form was inspected and complies with the R645 Coal Rules.

The Reclamation Agreement has been sent to the Division for review and signature.

The Mining and Reclamation Permit will expire on February 3, 2002. The bonding amount is \$3,238,000.

Inspector's Signature:

Stephen J. Demczak 🌶

Date: July 17, 2001

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd

cc: James Fulton, OSM

Rick Olsen, Canyon Fuel

Price Field office

 $O:\label{local_continuous_conti$